



ASAN

BUILDING SEWER STATUS

- ★ NON SEWERED WITHIN 200 ft FROM SEWER MAIN
- ★ NON SEWERED WITHIN 200 ft FROM SEWERED
- ★ NON SEWERED
- SEWERED
- UNIDENTIFIED
- ROADS
- SEWER MAINS




- Building Status
- Visited
- Sewered
- Unsewered
- Within 200 ft. From Sewered Building
- Within 200 ft. From Sewered Main



**Water and Environmental Research
Institute of the Western Pacific**

**UOG Station
Mangilao, Guam 96923**



UOG

