










YONA

BUILDING SEWER STATUS

-  NON SEWERED WITHIN 200 ft FROM SEWER MAIN
 -  NON SEWERED WITHIN 200 ft FROM SEWERED
 -  NON SEWERED
 -  SEWERED
 -  UNIDENTIFIED
-  ROADS
-  SEWER MAINS



Building Status



**Water and Environmental Research
Institute of the Western Pacific**

WERI

UOG Station
Mangilao, Guam 96923



UOG

